EXHIBIT C




FIGURE 6.17.7 Wood Wall Stude Showing Decreasing Damage as Distance from Fire Increases.